

Material Safety Data Sheet

Code No:00801

I.

Identity : Pearlized Paper

Manufacture's Name : NAN YA PLASTICS CORPORATION, CHIA-YI 2ND PLANT

*Plant Address : 201, SECTION 2, PEI-KANG RD, TAI-BAO , CHIA-YI ,
TAIWAN, R.O.C.*

Emergence Telephone Number : 886-5-2373711 ext.202

Telephone Number for information : 886-5-2373711 ext.202

Plant Manager : CHRIS LIN

Issue Date:2005/3/1

Revision Date :2014/7/2

II. Ingredients :

<u>Material</u>	<u>CAS NO</u>	
<i>1.Poly-Propylene</i>	<i>9003-07-0</i>	<i>92% ↑</i>
<i>2.Calclumcarbonate</i>	<i>471-34-1</i>	
<i>3.Titanium Dioxide</i>	<i>13463-67-7</i>	
<i>4.Silica</i>	<i>63231-67-4</i>	

III. Hazard Summary :

Physical Hazard : none

Health Hazard : none

IV. Physical / Chemical Characteristics :

Boiling Point : not applicable

Vapor Pressure : not applicable Evaporation Rate : not applicable

Vapor Density : not applicable Apperance : solid

Solubility in Water : insoluble Odor : no odor

V. Fire and Explosion Hazard Data :

Flash point : not applicable

Flammable Limit : not applicable

Extinguish Media : water fog, CO₂ foam, dry chemical

*Special Fire Fighting Procedures : in case of need, wear the fire protectors and
smokeproof respirators.*

Unusual Fire and Explosion Hazards : Nil

VI. Reactivity Data :

Stability : stable under normal conditons

Hazardous Decomposition or Byproducts : Nil

Hazardous Polymerization : will not occur

VII. Health Hazard Data :

Health Hazards (Acute and Chronic) : no relevant information found

Sings and symptoms of exposure : no relevant information found

Eye contact : mechanical injury only

Skin contact : mechanical injury only

*Ingestion : if large quantities are ingested, pump stomach in very case get
medical attention as required.*

VIII. Environmental and Disposal Information :

Action to take for spill and leaks : normal clean up procedure.

Waste disposal method : incinerate or land-fill, clean waste may be recycled.

IX. Special Protection Information :

*Ventilation : remove decompositon fumes with local exhaust if overheating occurs
during processing.*

*Handling : recommend use of forklift truck with probe when handing heavy roll
goods.*